

For more information contact Synergy Positioning Systems or visit the Synergy Positioning Systems website at [www.synergypositioning.co.nz](http://www.synergypositioning.co.nz)  
All branches: Phone 0800 867 266 Email: [info@synergypositioning.co.nz](mailto:info@synergypositioning.co.nz)

## Setup

1. Mount the display onto the bracket at the jaw mount.
2. Connect the power cable to the display.
3. The **Power** button has three functions:
  - Power on – press for one second
  - Power off – press for five seconds
  - 3D-MC Main Menu access – press anytime the display is powered on. The Main Menu will auto-hide after three seconds.
4. The **Zoom In/Out** buttons are active on any selected window.
5. Press the **Next View** button to switch the 3D-MC Main Screen at any time between **Plan, Section, or Profile** view.




Figure 1: GX-55/GX-75 Display – Front and Rear View